

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form Approved. OMB No. 2050-0039

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator ID Number KSD007246846		2. Page 1 of 1		3. Emergency Response Phone (800) 483-3718		4. Manifest Tracking Number 008037397 FLE			
		5. Generator's Name and Mailing Address Clean Harbors Kansas LLC 2549 North New York Street Wichita, KS 67219 Generator's Phone: (316) 269-7400						Generator's Site Address (if different than mailing address) SAME			
6. Transporter 1 Company Name Action Resources						U.S. EPA ID Number AIR000007237					
7. Transporter 2 Company Name						U.S. EPA ID Number					
8. Designated Facility Name and Site Address Clean Harbors Lone Mountain LLC 40355 S County Road 236 Wynoka, OK 73860 Facility's Phone: (580) 697-3500						U.S. EPA ID Number OKD065438375					
GENERATOR	9a. HM	9b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))				10. Containers		11. Total Quantity	12. Unit Wt./Vol.	13. Waste Codes	
						No.	Type				
	1	HA3077, HAZARDOUS WASTE, SOLID, N.O.S., (FOOL, F003), 9, PG III				1	DT	EST 16	Y	F001	F002
	2.									F004	F005
	3.										
4.											
14. Special Handling Instructions and Additional Information 1. CH821502X06 ERG#171 TR# TL#											
15. GENERATOR'S/OFFEROR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by the proper shipping name, and are classified, packaged, marked and labeled/placarded, and are in all respects in proper condition for transport according to applicable international and national governmental regulations. If export shipment and I am the Primary Exporter, I certify that the contents of this consignment conform to the terms of the attached EPA Acknowledgment of Consent. I certify that the waste minimization statement identified in 40 CFR 262.27(a) (if I am a large quantity generator) or (b) (if I am a small quantity generator) is true.											
Generator's/Offor's Printed/Typed Name J.M. Tyson											
Signature <i>Jim Tyson</i>											
Month Day Year 2 11 08											
TRANSPORTER	16. International Shipments <input type="checkbox"/> Import to U.S. <input type="checkbox"/> Export from U.S. Port of entry/exit: _____ Transporter signature (for exports only): _____ Date leaving U.S.: _____										
	17. Transporter Acknowledgment of Receipt of Materials										
	Transporter 1 Printed/Typed Name _____ Signature _____ Month Day Year _____										
	Transporter 2 Printed/Typed Name _____ Signature _____ Month Day Year _____										
DESIGNATED FACILITY	18. Discrepancy										
	18a. Discrepancy Indication Space <input type="checkbox"/> Quantity <input type="checkbox"/> Type <input type="checkbox"/> Residue <input type="checkbox"/> Partial Rejection <input type="checkbox"/> Full Rejection										
	Manifest Reference Number: _____										
	18b. Alternate Facility (or Generator) _____ U.S. EPA ID Number _____										
	Facility's Phone: _____										
18c. Signature of Alternate Facility (or Generator) _____ Month Day Year _____											
19. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems)											
1. H132 2. 3. 4.											
20. Designated Facility Owner or Operator: Certification of receipt of hazardous materials covered by the manifest except as noted in Item 18a											
Printed/Typed Name _____ Signature _____ Month Day Year _____											

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator ID Number KSD007246848	2. Page 1 of 1	3. Emergency Response Phone (800) 483-3718	4. Manifest Tracking Number 008037397 FLE		
5. Generator's Name and Mailing Address Clean Harbors Kansas LLC 2549 North New York Street Wichita, KS 67219			Generator's Site Address (if different than mailing address) SAME				
Generator's Phone: (316) 269-7400							
6. Transporter 1 Company Name Action Resources			U.S. EPA ID Number AIR000007237				
7. Transporter 2 Company Name			U.S. EPA ID Number				
8. Designated Facility Name and Site Address Clean Harbors Lone Mountain LLC 40355 S County Road 236 Warrick, OK 73860			U.S. EPA ID Number OKD065438376				
Facility's Phone: (580) 697-9500							
9a. HM	9b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))		10. Containers		11. Total Quantity	12. Unit Wt./Vol.	13. Waste Codes
			No.	Type			
x	1.	NA3077, HAZARDOUS WASTE, SOLID, N.O.S., (F001, F003), 9, PG III	1	DT	EST 16	Y	F001 F002 F003 F004 F005
	2.						
	3.						
	4.						
14. Special Handling Instructions and Additional Information 1. CH921502K0B ERG#1.71 TR# TL#							
15. GENERATOR'S/OFFEROR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by the proper shipping name, and are classified, packaged, marked and labeled/placarded, and are in all respects in proper condition for transport according to applicable international and national governmental regulations. If export shipment and I am the Primary Exporter, I certify that the contents of this consignment conform to the terms of the attached EPA Acknowledgment of Consent. I certify that the waste minimization statement identified in 40 CFR 262.27(a) (if I am a large quantity generator) or (b) (if I am a small quantity generator) is true.							
Generator's/Officer's Printed/Typed Name Jim Tyson		Signature <i>Jim Tyson</i>		Month 2		Day 11	
				Year 2015			
16. International Shipments <input type="checkbox"/> Import to U.S. <input type="checkbox"/> Export from U.S. Port of entry/exit: Date leaving U.S.:							
17. Transporter Acknowledgment of Receipt of Materials							
Transporter 1 Printed/Typed Name Don't C. Edwards		Signature <i>Don't C. Edwards</i>		Month 2		Day 11	
Transporter 2 Printed/Typed Name		Signature		Year 15			
18. Discrepancy							
18a. Discrepancy Indication Space <input type="checkbox"/> Quantity <input type="checkbox"/> Type <input type="checkbox"/> Residue <input type="checkbox"/> Partial Rejection <input type="checkbox"/> Full Rejection							
18b. Alternate Facility (or Generator) Manifest Reference Number: U.S. EPA ID Number							
Facility's Phone:							
18c. Signature of Alternate Facility (or Generator) Month Day Year							
19. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems)							
1. H132		2.		3.		4.	
20. Designated Facility Owner or Operator: Certification of receipt of hazardous materials covered by the manifest except as noted in Item 18a							
Printed/Typed Name Cathy Bradford		Signature <i>Cathy Bradford</i>		Month 12		Day 12	
				Year 15			